



Part I of Service Kit 1005372

Left Side of Aventura Shower Door



****Finish/color code must be specified when ordering.**

Part II of Service Kit 1005372 Right Side of Aventura Shower Door



****Finish/color code must be specified when ordering.**